


post development conditions 20170316

Prepared by Vanguard Engineering PC

HydroCAD® 10.00 s/n 06651 © 2013 HydroCAD Software Solutions LLC

Type II 24-hr 10-year event Rainfall=3.25"

Printed 3/16/2017




post development conditions 20170316

Prepared by Vanguard Engineering PC

HydroCAD® 10.00 s/n 06651 © 2013 HydroCAD Software Solutions LLC

Type II 24-hr 100-year event Rainfall=5.59"

Printed 3/16/2017



post development conditions 20170316

Prepared by Vanguard Engineering PC

HydroCAD® 10.00 s/n 06651 © 2013 HydroCAD Software Solutions LLC

Type II 24-hr 1-year event Rainfall=1.91"

Printed 3/16/2017

